

| 25X1 | | | | | 1. 1 |
|-----------------------------|--|--|-----|-------------------------|------|
| CONFIDERITIAL | | | 25> | ⁽¹ Attachmen | t 3 |
| CENTRAL INTELLIGENCE AGENCY | | | | Page 2 | |

I egend:

- 1. Two open-hearth furnaces, each 2.5 meters high and each with a base like meters. Source himself was employed on the reconstruction of one of the furnaces. The two furnaces had a charging crane serving them both. The furnaces were fueled with oil injected under pressure through a nozale
- 2. Three electric furnaces, each 2 meters high and 1.3 meters in diameter.
 Source reported "electrically heated converters". Four or five easting ladies, each 3 meters high and 2 meters in diameter, were used for the castings. The open-hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with scrap, higher hearth furnaces and the electric furnaces were charged with high electric furnaces and the electric furnaces were charged with high electric furnaces and the electric furnaces and the electric furnaces and the electric furnaces and heavy, silvery naterial which source hearth furnaces and heavy, silvery naterial which sourc
- 3. Six molding machines, set up in a separate section of the shop.
- 4. Two shaking grates on which small castings were cleaned. Source worked at these grates.
- 5. Three shaking grates on which large eastings were cleaned. A conveyor belt ran in a conduit under the grates removing the molding sand falling through on it.
- 6. One magnetic crane, running outside the building, along the eastern side of the workshop. There were also two traveling cranes, a small one running at a medium height from the floor, and a heavy one running above the founding furnaces. Moother traveling crane was in the molding shop and a small crane was in the center of the workshop.
- 7. Forge, housed in a separate section. Letails are not known.

| | 25X1 | | | . • |
|-------------|------|--|--|-----|
| colpicultly | | | | |